

# Vulnerability found in a VT STUDIO function

Published on March 29, 2024

KEYENCE CORPORATION

## ■ Overview

A DLL loading vulnerability has been found in VT STUDIO.

The affected versions of VT STUDIO are listed below.

## ■ How to check if your software is affected:

The affected products and versions are as follows:

Product name	Version
VT STUDIO	Ver.8.32 and earlier

To check your software's version, refer to the steps below.

Go to Menu and select Help > Version information. The Version information dialogue box will open.

## ■ Description of the vulnerability

The affected products contain a DLL loading vulnerability.

## ■ Threats posed by the vulnerability

Attackers may be able to execute arbitrary code by exploiting this security issue.

## ■ Countermeasure

The countermeasure is as follows:

Product name	Countermeasure
VT STUDIO	Update the software to Ver.8.33 or later.

## ■ Contact information

Please contact your nearest KEYENCE office.